

PRODUCT ADVISORY

3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harnesses

ANSI & OSHA Versions


This is not a recall, the 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harnesses remain safe for use. As part of 3M Fall Protection's ongoing commitment to delivering high quality safety equipment, we are notifying our customers of the following information related to the 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harnesses portfolios. During internal testing of certain 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harness models, we found that a percentage of tested units did not meet the ANSI Z359.11, Section 3.2.2.3.1 dynamic requirement on the front (sternal) D-ring. This test and the resulting forces are not representative of what would be seen in real world application (i.e. when attached to a vertical cable sleeve with an energy absorbing device).



The 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harnesses remain safe for use. In all tests, these harnesses meet all static requirements and dynamic testing that simulates a real-world application. Variability in the supplied D-ring contributed to the test results seen. This issue has been corrected on harnesses produced after May 1, 2021. We are not aware of any accidents, injuries, or customer complaints related to the condition described above.

Affected 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harnesses can be found by accessing the link: <http://go.3M.com/XOHarnessSternalDRingAdvisory>

End Users: If this notice of non-compliance to the ANSI requirement is of concern to you, please inspect your Cross Over Style Harness label(s) (see photograph to right) to determine if it is one of the affected part numbers and was manufactured before May 1, 2021. Once you have confirmed the part number & affected date, please contact 3M Customer Service at 1-833-638-2697 or at 3musfbserviceaction@mmm.com and provide us with contact information. We will have someone contact you to discuss the following remediation options:



1. Remediate your product(s) at your location.
 - 3M will ship D-ring sleeve(s) and instructions for application of the D-ring sleeve(s) directly to you at 3M's expense.
2. Return affected product(s) to 3M for remediation by 3M.
 - A UPS shipping label will be created for you to facilitate the return of your affected product(s).
 - Returned product must pass a pre-use inspection. If it passes the inspection, 3M will apply the D-ring sleeve(s) to your harness(es) and return the remediated product to you at 3M's expense. If it fails inspection, we will dispose of the product and contact you.

If you have any questions regarding this notice, please contact the 3M Fall Protection Customer Service Team at 3musfbserviceaction@mmm.com or call 1-833-638-2697.

Distributors: Please contact our Customer Service department at 1-833-638-2697 or at 3musfbserviceaction@mmm.com to obtain a listing of all affected 3M™ DBI-SALA® Delta™, ExoFit™, ExoFit™ Plus & ExoFit™ XP Cross Over Style Harness(s) sold to you. Please forward this "Product Advisory" to any of your customers/users who have purchased the harnesses listed above from you. If you have any inventory of the affected models, please contact our Customer Service department to have them returned.