

SAFETY RECALL

**Pelican 9410L Flashlight (Part # 9410-021-245 or 9410-021-110)
Pelican Replacement Battery Pack (Catalog #9419L,
Part # 9413-301-001)
can overheat, posing a fire hazard**

Stop Using The Flashlights and Battery Packs Immediately



Pelican Replacement Battery Pack
(Catalog #9419L)



Pelican 9410L Flashlight in yellow

To identify recalled products, check the part number and for a manufacture date between May 2014 and March 2015 on the original packaging. Without the original packaging, check the battery pack itself. To view the battery packs in flashlights, remove the 6 screws at the bottom of the flashlight; remove the black plastic covering; then unscrew the metal bracket and gently lift the bracket to uncover the battery pack and view the part number. Battery packs that contain green wrapped cells (versus gray or brown wrapped cells) need to be replaced.

**Contact Pelican Products, Inc., 8 AM-5 PM PT, Monday
through Friday at (toll free) (877) 619-0289, (310) 257-
5691, or via e-mail at 9410L@pelican.com**

**for instructions on how to return the recalled product and receive a replacement
battery pack. For more information visit <http://www.pelican.com> and click on
“Recall Information”**