










# Hypertherm®

## Powermax®

### Product line overview



|                          |   | Powermax30 XP | Powermax30 AIR | Powermax45 XP   | Powermax65 | Powermax85 | Powermax105 | Powermax125 |
|--------------------------|---|---------------|----------------|-----------------|------------|------------|-------------|-------------|
| Cut capacity             | Recommended   | 3/8"          | 5/16"          | 5/8"            | 3/4"       | 1"         | 1-1/4"      | 1-1/2"      |
|                          | Severance   | 5/8"          | 5/8"           | 1-1/8"          | 1-1/4"     | 1-1/2"     | 2"          | 2-1/4"      |
|                          | Output range  | 15-30         | 15-30          | 10-45           | 20-65      | 25-85      | 30-105      | 30-125      |
|                          | Input phase   | Single        | Single         | Single or three | Three      | Three      | Three       | Three       |
| Application capabilities |  Mechanized cutting    |               |                | •               | •          | •          | •           | •           |
|                          |  Drag cutting         | •             | •              | •               | •          | •          | •           | •           |
|                          |  FineCut®            | •             |                | •               | •          | •          | •           | •           |
|                          |  Marking             |               |                | •               |            |            |             |             |
|                          |  Precision gouging   |               |                | •               |            |            |             |             |
|                          |  Max control gouging |               |                | •               | •          | •          | •           | •           |
|                          |  Max removal gouging |               |                |                 | •          | •          | •           | •           |
|                          |  HyAccess™           | •             |                | •               | •          | •          | •           | •           |
|                          |  FlushCut™           |               |                | •               | •*         | •*         | •*          | •           |

\*Using the 45 A FlushCut consumables above 45 amps on the Powermax65/85/105 will cause premature consumable damage.